

CLEANING AGENT**CLEAN-100**

Application: For the removal of dirt and burned adhesive residues from melting tanks, glue pots, and coating equipment.

Usage: Drain the melting tank and remove old adhesive residues using a wooden spatula. The adhesive should be removed manually as completely as possible. Fill the unit with cleaning agent and allow it to melt. Heat to 160–180°C and maintain for approximately 30 minutes. Ensure the cleaning agent is completely removed before resuming operation.

Specification:

Polymer basis	Oxidized Polyethylene (OPE)
Application Temperature	160 - 180°C
Viscosity at 140°C (mPa s)	20,000 ± 6,000
Supply form	White flakes
Softening range	90-100 °c

Packaging & Storage: in a 25 kg kraft bag. 40 bags/ pallet
Shelf life of 24 months, in original package, cool and dry

Remarks: All data indicated are characteristics represented as average values. Our technical data sheets are revised to represent the latest information. This edition is valid on the date of compilation.

**TIANJIN SHENG-WANG ELECTRONIC
CHEMICAL PLANT**

E-mail: sales@swadhesive.com

www.swhotmeltglue.com

FREE BIRD 
Adhesives